



B SAFE SAFETY & SECURITY CONSULTANCY

INSPECTION, TRAINING, CONSULTANTS

Thorough Examination Report For Webbing Sling

Company Name:	Aztec Middle East	Contact Person	Suresh	Contact Number	0569900267
	Contracting LIc				
Project Name	Canal Garden Site	Location	Dubai, Warsan, Canal	Inspector name	Mohammed Asharaf
			Garden Site		
Inspection Item	Webbing Sling	Date of Inspection	2020-12-26	Date of Expiry	NA
Certificate	BSS-1057	Type of	Periodic Inspection	Status	Unsafe
Number		Inspection			
Location Details	Canal Garden Substation	Revision	0	Workorder	343

webbing sling -Description						
Туре	FLat	Manufacture	GULF METAL			
Material	Polyester	Effective working length	2			
Width	2inch	Safety factor	7:1			
Working load limit (straight hitch)	Na					
Quantity	02	Serial number(s)	F185,F186			
Additional information	Found cuts	Previous inspection date	NA			
Accredited Standard	BS EN 1492-1 2000+A1:2008 , BS EN 1492 -2 2000+A1:2008, BS EN 1492 -	Number of layers	02			
	4 2000+A1:2008					
Defects						

All the inspections results relates exclusively to work ordered or objects or lot inspected and inspection certificates/reports shall not be reproduced except in full without approval of inspection body and the client. B SAFE has legal indemnity against all losses, accidents and damages on site arising due to faulty inspection activities during the work. we certify on behalf of B SAFE SAFETY & SECURITY CONSULTANCY that the item(s)/equipment described in this certificate is/are

Unsafe TO USE

and that the particuler details are correct.

B Safe is a third party inspeciton Type A Inspection Body

The item/equipment should be re-tested in case of any major repair and/or althernation at the above details/description.

ENG. Mohammed Asharaf

Found cut and chafing



Deputy Technical Manager

defect description

Inspection Details

Webbing sling - checklist summery					
Legible Markings	Safe				
Color coding of label	GREEN				
Signs surface chafe	Unsafe				
Signs of local Abrasion	Safe				
longitudinal and cross cuts in webbing	Safe				
Damaged stitching	Unsafe				
signs of chemical attack and heat and friction damage	Safe				
Weld splatter burns	Safe				

In providing services information or advice B SAFE safety consultancy does not warrant the accuracy of any information or advice supplied by the end user, and shall not be liable for any loss, damage or expense whatever sustained by any person due to any act of mis-operation/ mis-handled.

It should be also understood and agreed that all contained information in this report shall not be considered to relieve any designer, manufacturer, supplier, seller, repairer or operator of any warranty, expressed or implied.

B SAFE safety consultancy will not support the validity of any certificate if it has been found that the item descriped has been mistreated, overloaded, impact loaded, misoperated, misused or shock loaded.

This certificate is the property of B safe safety & security consultancy and shall be retuned on demand.

THIS REPORT HAS BEEN ISSUED WITHOUT PREJUDICE TO ANY PARTY INVOLVED

Inspection Images



