

B SAFE SAFETY & SECURITY CONSULTANCY

INSPECTION, TRAINING, CONSULTANTS

Thorough Examination Certificate For Cradle

Company Name:	Arizona Equip Tr Llc	Contact Person	Rajesh	Contact Number	0568289071
Project Name	Tak Construction Site, Jvc	Location	Park View Tower Jvc	Inspector name	Omar Masoud
Inspection Item	Cradle	Date of Inspection	2021-01-09	Date of Expiry	2021-07-09
Certificate Number	BSS-1857	Type of Inspection	Periodic Inspection	Status	Safe
Location Details	Jvc Dubai	Revision	0	Workorder	795

Cradle-Description						
Manufacture	X platform	Model	Zlp630			
Serial number(Platform)	CI2	S. No motors	80025			
			604420			
S. No safety devices	0609258	Span	1m			
	45160					
Operation height	From 1st floor to 11st flor	Safe working load (SWL)	125kg			
Proof load applied	187.5 kg	Elevation	Good			
Support description	Up standing beam fixed to the wall by	Location	Right elevation			
ı	4 bolts					
Grindlines(if provided)	N/A	Accredited Standard and Procedure	BS EN 1808:2015 , BSS-INPR-			
<u> </u>			002			
NDT (If required)	N/A	Instruments used in inspection	N/A			
Subcontract Parts	Arezona	Environment Conditions during	Good			
ı		inspection				
Last Inspection Date	N/A	Additional comments (If any)	N/A			
Any major repair if found / detail	N/A					
Defects						

All the inspections results relates exclusively to work ordered or objects or lot inspected and inspection certificates/reports shall not be reproduced except in full without approval of inspection body and the client. B SAFE has legal indemnity against all losses, accidents and damages on site arising due to faulty inspection activities during the work. we certify on behalf of B SAFE SAFETY & SECURITY CONSULTANCY that the item(s)/equipment described in this certificate is/are

Safe TO USE

and that the particuler details are correct.

B Safe is a third party inspeciton Type A Inspection Body

The item/equipment should be re-tested in case of any major repair and/or althernation at the above details/description.

Please note that Below Signature & Stamping are generated & Approved Electronically.

Inspection Engineer ENG. Omar Masoud



Deputy Technical Manager ENG. Usman Amjad

ENG-CR-2/V8/2020-12-28

Tel: +971 4 320 94 94 FAX: +971 4 320 94 95 P.O.BOX: 300465 DUBAI - UAE E.MAIL: info@bsafesafety.com DUBAI SILICON OASIS - PALACE TOWER 1

www.bsafesafety.com

defect description

Inspection Details

Cradle-Electrical Test					
No damage to panel enclosure	Safe				
Condition of the wires and distribution board					
Cradle-Suspended Platform					
Guardrails, intermediate rails and toe boards shall be free for deformation or distortion or missing					
Wall rollers , caster wheels					
Cradle-Hoisting System					
Service brake activated, no displace found under normal working conditions.					
No power descent , maximum angle is 14deg					
Tensioning device for wire rope					
Cradle-Limit Switches					
Anti-tilt device	Safe				
Lifting limit switch					
All of trolley motions (traversing, slewing, and telescoping) shall be provided with limit switch.					
Cradle-General Requirements					
Labeling for SWL , and WLL on the hoist					
Serial numbers of hoists , secondary devices and control box					
Electrical wiring diagram for the control box					
Warning signs inside the platform					

In providing services information or advice B SAFE safety consultancy does not warrant the accuracy of any information or advice supplied by the end user, and shall not be liable for any loss, damage or expense whatever sustained by any person due to any act of mis-operation/ mis-handled.

It should be also understood and agreed that all contained information in this report shall not be considered to relieve any designer, manufacturer, supplier, seller, repairer or operator of any warranty, expressed or implied.

B SAFE safety consultancy will not support the validity of any certificate if it has been found that the item descriped has been mistreated, overloaded, impact loaded, misoperated, misused or shock loaded.

This certificate is the property of B safe safety & security consultancy and shall be retuned on demand.

THIS REPORT HAS BEEN ISSUED WITHOUT PREJUDICE TO ANY PARTY INVOLVED