

# **B SAFE** SAFETY & SECURITY CONSULTANCY

#### INSPECTION, TRAINING, CONSULTANTS

### **Thorough Examination Certificate For Concrete Bucket**

| Company Name:      | Aztec Middle East Contracting | Contact Person     | Suresh              | Contact Number | 0569900267   |
|--------------------|-------------------------------|--------------------|---------------------|----------------|--------------|
|                    | LIC                           |                    |                     |                |              |
| Project Name       | Makhazen 132/11 Kv Substation | Location           | Jafza, Dubai        | Inspector name | Aamir Hassan |
| Inspection Item    | Concrete Bucket               | Date of Inspection | 2020-12-31          | Date of Expiry | 2021-06-30   |
| Certificate Number | BSS-1003                      | Type of Inspection | Periodic Inspection | Status         | Safe         |
| Location Details   | Makhazen 132/11 Kv Substation | Revision           | 0                   | Workorder      | 507          |
|                    | Jafza Dubai                   |                    |                     |                |              |

| Jaiza Dabai                         |                          |                       |          |                        |  |  |  |  |
|-------------------------------------|--------------------------|-----------------------|----------|------------------------|--|--|--|--|
| Concrete Bucket-Description         |                          |                       |          |                        |  |  |  |  |
| Material Steel                      |                          |                       |          |                        |  |  |  |  |
| Type of joints (welded.bolted,bend) | Welded                   |                       |          |                        |  |  |  |  |
| Number of lifting points            | 4                        |                       |          |                        |  |  |  |  |
| Diameter of the lifting point       | 50 mm                    |                       |          |                        |  |  |  |  |
| Dimensions (W x L x H)              | 1.1m × 1.1m × 1.2 m      | 1.1m × 1.1m × 1.2 m   |          |                        |  |  |  |  |
| Safe working load                   | 2000 kg                  |                       |          |                        |  |  |  |  |
| Quantity                            | 1                        | 1                     |          |                        |  |  |  |  |
| Identification number               | CB-33                    |                       |          |                        |  |  |  |  |
| Inspection equipment                | MT-35 DC-36 LDM-35 SL-03 | Previous inspection   |          | 6.2020<br>en crescent) |  |  |  |  |
| NDT (report number/test method)     | N/a                      | Additional informatio | Pad 20 m | eye thickness :<br>m   |  |  |  |  |
| Reference standard                  | BS EN 13155:2003+A2:2009 |                       |          |                        |  |  |  |  |
| <b>Defects</b>                      |                          |                       |          |                        |  |  |  |  |
|                                     |                          |                       |          |                        |  |  |  |  |

All the inspections results relates exclusively to work ordered or objects or lot inspected and inspection certificates/reports shall not be reproduced except in full without approval of inspection body and the client. B SAFE has legal indemnity against all losses, accidents and damages on site arising due to faulty inspection activities during the work. we certify on behalf of

B SAFE SAFETY & SECURITY CONSULTANCY that the item(s)/equipment described in this certificate is/are

#### Safe TO USE

and that the particuler details are correct.

B Safe is a third party inspeciton Type A Inspection Body

The item/equipment should be re-tested in case of any major repair and/or althernation at the above details/description.

ENG. Aamir Hassan



Deputy Technical Manager ENG. Usman Amjad

ENG-CH-47/V1/2020-12-19

Tel: +971 4 320 94 94 FAX: +971 4 320 94 95 P.O.BOX: 300465 DUBAI - UAE E.MAIL: info@bsafesafety.com DUBAI SILICON OASIS - PALACE TOWER 1

www.bsafesafety.com

defect description

## **Inspection Details**

| Concrete Bucket-checklist summery                 |      |  |  |  |  |
|---|------|--|--|--|--|
| bucket body                                       | Safe |  |  |  |  |
| lifting handle/point                              | Safe |  |  |  |  |
| signs for deformation /cracks /holes / distortion | Safe |  |  |  |  |
| concrete discharge technique                      | Safe |  |  |  |  |
| safety latch/lock on bail                         | Safe |  |  |  |  |

In providing services information or advice B SAFE safety consultancy does not warrant the accuracy of any information or advice supplied by the end user, and shall not be liable for any loss, damage or expense whatever sustained by any person due to any act of mis-operation/ mis-handled.

It should be also understood and agreed that all contained information in this report shall not be considered to relieve any designer, manufacturer, supplier, seller, repairer or operator of any warranty, expressed or implied.

**B SAFE safety consultancy** will not support the validity of any certificate if it has been found that the item descriped has been mistreated, overloaded, impact loaded, misoperated, misused or shock loaded.

This certificate is the property of B safe safety & security consultancy and shall be retuned on demand.

THIS REPORT HAS BEEN ISSUED WITHOUT PREJUDICE TO ANY PARTY INVOLVED