

Thorough Examination Certificate For Fall Arrest Harness

Company Name:	Amafha General Trading (Vsix-jv)	Contact Person	Sugra	Contact Number	0555323611
Project Name	Dut	Location	Besix Site, Dut, Jlt, Dxb,uae	Inspector name	Rejin Antony
Inspection Item	Retractable Fall Arrester	Date of Inspection	2021-01-09	Date of Expiry	2021-07-08
Certificate Number	BSS-1813	Type of Inspection	Periodic Inspection	Status	Safe
Location Details	Besix Site, Dut, Jlt, Dxb,uae	Revision	0	Workorder	783

Fall arrest harness-Description.

Description	Manufacture: Vaultex Model: Proton 10 Rope length: 10m Rope diameter: 4.8mm Origin:India Color: Black SWL: 100kg
Identification number(s)	1)V834, 2)V845, 3)V849, 4)V858, 5)V838, 6)V839, 7)V846, 8)V854, 9)V840, 10)V853, 11)V757, 12)V745
Quantity	12
Environments conditions	Good Condition
Sub-contractor	Nil
Accredited Standards	BS EN 361:2002, BS EN 12277:2015, BS EN 358:2018, BS EN 813:2008, ANSI/ASSE Z359.1 ,INPR-34
Additional comments	Nil
Defects	
defect description	Nil

All the inspections results relates exclusively to work ordered or objects or lot inspected and inspection certificates/reports shall not be reproduced except in full without approval of inspection body and the client. B SAFE has legal indemnity against all losses, accidents and damages on site arising due to faulty inspection activities during the work. we certify on behalf of **B SAFE SAFETY & SECURITY CONSULTANCY** that the item(s)/equipment described in this certificate is/are

Safe TO USE

and that the particuler details are correct.

B Safe is a third party inspeciton Type A Inspection Body

The item/equipment should be re-tested in case of any major repair and/or althervation at the above details/description.

Please note that Below Signature & Stamping are generated & Approved Electronically.

ENG. Rejin Antony



Deputy Technical Manager

ENG. Usman Amjad

Inspection Details

Fall arrest harness- checklist Summery	
buckles, grommets, D-rings for damage, broken, distorted, and must be free of sharp edges, burrs, cracks, worn parts, corrosion, and contamination	Safe
D-rings must be integral to the harness and pivot freely, and all buckles must connect and adjust as intended	Safe
webbing for rips, tears, fraying, and discoloration	Safe
stitching is in-tact, broken, is fraying , friction on the harness	Safe
cuts, swelling, damage and wear due to use, to heat, and to contact with chemicals	Safe
broken stitches may be an indication that the harness has been impact loaded	Safe
Textile & metal attachment points (marks, cracks, wear, deformation, corrosion	Safe
Connector mechanism for any signs of deformation of body distortion, closing mechanism or incorrect functionality	Safe

In providing services information or advice B SAFE safety consultancy does not warrant the accuracy of any information or advice supplied by the end user , and shall not be liable for any loss, damage or expense whatever sustained by any person due to any act of mis-operation/ mis-handled.

It should be also understood and agreed that all contained information in this report shall not be considered to relieve any designer, manufacturer, supplier, seller, repairer or operator of any warranty, expressed or implied.

B SAFE safety consultancy will not support the validity of any certificate if it has been found that the item described has been mistreated, overloaded, impact loaded, misoperated, misused or shock loaded.

This certificate is the property of B safe safety & security consultancy and shall be returned on demand.

THIS REPORT HAS BEEN ISSUED WITHOUT PREJUDICE TO ANY PARTY INVOLVED

ENG-CH-23/V1/2020-12-18

Tel : +971 4 320 94 94 FAX: +971 4 320 94 95 P.O.BOX : 300465 DUBAI - UAE

E.MAIL : info@bsafesafety.com DUBAI SILICON OASIS - PALACE TOWER 1

www.bsafesafety.com

Inspection Images



ENG-CR-23/V1/2020-12-18

Tel : +971 4 320 94 94 FAX: +971 4 320 94 95 P.O.BOX : 300465 DUBAI - UAE

E.MAIL : info@bsafesafety.com DUBAI SILICON OASIS - PALACE TOWER 1

www.bsafesafety.com